IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re the Reissue Patent of:

Reissue Patent: RE38,382

Inventor(s):   M. MIYAHARA et al.

Serial No.:   09/930,437

Filed: August 16, 2001

For: HEAT SINK AND ELECTRONIC DEVICE EMPLOYING THE SAME

TRANSMITTAL OF CERTIFICATE OF CORRECTION

Assistant Commissioner of Patents
Washington, DC   20231

Sir:

The present reissue patent issued from an application that is one of a family of divisional reissue applications resulting from Patent No. 5,940,268. The present reissue patent issued without the cross reference to the other reissue application of the family which is required pursuant to 37 CFR 1.177(a). Accordingly, the attached Certificate of Correction is filed to correct this error.

Respectfully submitted,

/James Edward Ledbetter/

Date: November 14, 2007   James E. Ledbetter
JEL/att   Registration No. 28,732

ATTORNEY DOCKET NO. JEL 30347A-RE-DIV
STEVENS, DAVIS, MILLER & MOSHER, L.L.P.
1615 L Street, NW, Suite 850
P.O. Box 34387
Washington, DC   20043-4387
Telephone: (202) 785-0100
Facsimile: (202) 408-5200

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO.   :   RE38,382

DATED   : January 13, 2004

INVENTOR(S) : Masaharu MIYAHARA, Yasushi INOUE and Kenji SUGA

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 1, between lines 7 and 8, please insert the following text as the first sentence of the specification:

Notice: More than one reissue application has been filed for the reissue of Patent No. 5,940,268. The reissue applications are application number 09/930,437, filed August 16, 2001 and issued as RE38,382 (the present application), and application number 10/667,336, filed September 23, 2003, both of which are divisional reissues of Patent No. 5,940,268.

MAILING ADDRESS OF SENDER (Please do not use customer number

1615 L Street, NW
Suite 850
Washington, D.C.
20036

PATENT NO. RE38,382

No. of additional copies

➔